



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: 05/12/2016

Reviewed

ASIS

Mine Name: County Canyon Shale	Permit Number: M/023/0024	Mine Status: Active
Operator Name: Ash Grove Cement Company	Inspection Date: 04/28/2016	Permit Fees: Paid
Inspector(s): Wayne Western	Inspection Time: 9:50 - 10:00 am	Bond Amount: \$166,000
Attendee(s): Josh Nelson	Weather:	Bond Escalation: 07/19/2017
Inspection Purpose: Routine inspection		Prior Inspection: 04/07/2015

Conclusions and Recommendations

The pit was idle in 2013 and 2014. The Operator did haul material off site during those years. The Operator mined 12,609 cy in 2015. Camera was not working.

Elements of Inspection	Evaluated & Commented	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input type="checkbox"/>
The fees and bond are current		
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
There are no shafts or adits at the site. Highwalls are stable.		
3. Protection of Drainages/Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Runoff is contained in the pit.		
4. Deleterious Material	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No mining materials are on site.		
5. Roads (maintenance, surfacing, dust control, safety)	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Roads are in good working condition.		
6. Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No reclamation occurred at the site in 2014.		
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature:

Wayne Western

CC: jmccarth@blm.gov

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M023-Juab/M0230024-CountyCanyon/Inspection/Insp-04282016.pdf